

Tech-Tip: Proper Installation of a Cord Pipe Cover

The "Cord Pipe Cover" plays a critical role in proper fountain assembly. This part prevents leaks and extends the fountain run time before needing to refill.



The picture to the left illustrates an **improper assembly** and is an example of what NOT to do.

The missing Cord Pipe Cover and the lack of a proper 'drip-loop' with the light cord will result in water leaking down the cord pipe, leading to very rapid water loss.



The picture to the left shows the **proper way** to assemble the fountain.

The Cord Piper Cover is now properly installed over the pipe protecting from any water that may drip down from above.

Additionally, the light cord has been installed with some additional slack so that it creates a 'drip-loop' down in to the reservoir before it exits the fountain via the cord pipe.

These 2 important steps will prevent the occurrence of water loss down the cord pipe and greatly increase the run-time of your fountain.

Having problems setting up your fountain?
Call us toll free at 1-855-826-4356 or email info@angelodecor.com